

NORTH 1/4 CORNER SECTION 22, TOWNSHIP 21 SOUTH, RANGE 10 EAST

- 1) ON PAGE 258 OF THE GLO ORIGINAL FIELD NOTES IN THE DRAFTING ROOM IN THE COUNTY ENGINEER'S OFFICE IT STATES THAT **THEY SET A LIMESTONE 26" X 12" X 3"** FOR THE 1/4 CORNER BETWEEN SECTIONS 15 & 22-21-10.
THE GOVERNMENT SURVEY NOTES SHOW THE FOLLOWING INFORMATION:
 - 1) 40.10 CHAINS WEST TO THE 25" X 17" X 3" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 15, 16, 21 & 22-21-10
 - 2) 40.10 CHAINS EAST TO THE 24" X 12" X 3" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 14, 15, 22 & 23-21-10

- 2) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN SURVEY F15001 IN THE SURVEY FILE FOR TOWNSHIP 20-10 FOR THE SURVEY OF TWO TRACTS IN THE SOUTHWEST QUARTER OF SECTION 15-21-10, FOR PROJECT NUMBER 99208-02 DATED OCTOBER 6, 1999, SAID IN HIS *SURVEY NOTES* THAT THE SOUTH 1/4 CORNER OF SECTION 15-21-10 WAS DEEMED **LOST** IN NORTH-SOUTH POSITION AS IT FELL ON A DRAINAGE CULVERT. HE DID **NOT** RESET THE SOUTH 1/4 CORNER OF SECTION 15-21-10 ON THIS SURVEY.

NORTH QUARTER CORNER 22-21-10