

**NORTH 1/16TH CORNER OF THE NORTHEAST QUARTER OF SECTION 16, TOWNSHIP 18 SOUTH, RANGE 11 EAST**

- 1) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED MAY 28, 2003, FOR PROJECT NUMBER 03197-02, SURVEY F09001 IN THE SURVEY FILE FOR TOWNSHIP 18-11 FOR A SUBDIVISION OF THE SOUTHEAST QUARTER OF SECTION 9-18-11, SAID THAT **HE SET A 1/2" X 24" REBAR WITH HIS "LS 752" CAP** FOR THE SOUTH 1/16<sup>TH</sup> CORNER OF THE SOUTHEAST 1/4 OF SECTION 9 ON TRUE LINE AND HALF WAY BETWEEN THE SOUTH 1/4 CORNER AND THE SOUTHEAST CORNER OF SECTION 9.
  - 1) 34.0' NE TO A CONCRETE NAIL & WASHER IN A FENCE POST
  - 2) 24.6' NW TO A CONCRETE NAIL & WASHER IN A FENCE TIE POST
  - 3) 20.0' NORTH TO A 1/2" X 24" REBAR WITH HIS CAP SET
  - 4) 17.0' SOUTH TO A LINE OF FENCE EAST-WEST
  - 5) 3.0' NORTH TO THE CENTERLINE TRAVELED WAY OF ROAD 230 EAST-WEST

**HIS SURVEY DRAWING SHOWS THE FOLLOWING DISTANCES:**

  - 1) 1,299.12' WEST TO A 1/2" REBAR OVER THE STONE FOUND AT THE SOUTHWEST CORNER OF THE SE1/4 OF SECTION 9
  - 2) 1,299.12' EAST TO A 5/8" REBAR WITH A LYON COUNTY CAP SET FOR THE SOUTHEAST CORNER OF THE SE1/4 OF SECTION 9
  - 3) 1,319.62' NORTH TO A 1/2" REBAR WITH HIS "LS 752" CAP SET FOR THE CENTER OF THE SE1/4 OF SECTION 9
  - 4) 2,639.24' NORTH TO A 1/2" REBAR WITH HIS "LS 752" CAP SET FOR THE 1/16<sup>TH</sup> CORNER ON THE NORTH SIDE OF THE SE1/4 OF SECTION 9

NORTH SIXTEENTH CORNER NORTHEAST QUARTER 16-18-11