

NORTH 1/4 CORNER SECTION 33, TOWNSHIP 18 SOUTH, RANGE 11 EAST

- 1) ON PAGE 341 OF THE GLO ORIGINAL FIELD NOTES IN THE DRAFTING ROOM IN THE COUNTY ENGINEER'S OFFICE IT STATES THAT **THEY SET A LIMESTONE 15" X 12" X 3"** FOR THE 1/4 CORNER BETWEEN SECTIONS 28 & 33-18-11.
THE GOVERNMENT SURVEY NOTES SHOWS THE FOLLOWING INFORMATION:
 - 1) 40.05 CHAINS WEST TO THE 22" X 21" X 3" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 28, 29, 32 & 33-18-11
 - 2) 40.05 CHAINS EAST TO THE 17" X 12" X 5" LIMESTONE THE SET FOR THE CORNER TO SECTIONS 27, 28, 33 & 34-18-11

- 2) G. M. WALKER, BRECKENRIDGE COUNTY SURVEYOR FROM 1857 TO 1860, IN SURVEY NUMBER 2 RECORDED IN SURVEY BOOK "A" ON PAGE 3, A **PERMANENT SURVEY** DATED DECEMBER 31, 1857 TO ESTABLISH THE CENTER POST OF SECTION 33-18-11 AND ALSO THE SOUTHWEST AND SOUTHEAST CORNERS OF THE NORTH 1/2 OF THE SOUTHEAST 1/4 OF SAID SECTION 33, SAID THAT **HE FOUND THE STONE 1/4 POST** ON THE NORTH LINE OF SECTION 33-18-11 ON THIS **PERMANENT SURVEY**.
HIS SURVEY NOTES SHOW THE FOLLOWING INFORMATION:
 - 1) 40.34 CHAINS SOUTH TO THE STONE POST HE SET FOR THE PERMANENT CENTER CORNER OF SECTION 33-18-11
 - 2) 60.51 CHAINS SOUTH TO THE STONE POST HE SET FOR THE PERMANENT SOUTHWEST CORNER OF THE N1/2 OF THE SE1/4 OF SECTION 33-18-11
 - 3) 80.68 CHAINS SOUTH TO THE STONE 1/4 POST HE FOUND ON THE SOUTH LINE OF SECTION 33-18-11 ON THE TOWNSHIP LINE

- 3) STEVEN S. BROSEMER, L.S. 752, IN A LAND SURVEY REFERENCE REPORT DATED JULY 7, 1983, SAID THAT HE SEARCHED FOR AND PRODDED FOR THE STONE AT THE SOUTH 1/4 CORNER OF SECTION 28-18-11 THAT WAS FOUND BY ALVA J. SMITH IN 1902 IN SURVEY BOOK "E" ON PAGE 233, BUT HE DID **NOT** FIND THE STONE. HE CONSIDERED THAT THE SOUTH 1/4 CORNER OF SECTION 28-18-11 WAS **LOST**. HE SET A 60 D NAIL FOR THE "APPARENT" CORNER FROM THE PHYSICAL EVIDENCE THAT HE FOUND AT THIS CORNER; I.E. IN LINE WITH TREE STUMPS & FENCING TO SOUTH AND 17' NORTH OF EVIDENCE OF FENCE EAST-WEST, BUT HE DID **NOT** RESET THE SOUTH 1/4 CORNER OF SECTION 28-18-11 AT THIS TIME.

- 4) STEVEN S. BROSEMER, L.S. 752, IN SURVEY F28001 IN THE SURVEY FILE FOR PROJECT 85076 DATED JULY 9, 1985 AND RECORDED IN VOLUME 417 ON PAGE 644 IN THE REGISTER OF DEEDS OFFICE, SAID THAT HE DID **NOT** SEARCH AGAIN FOR THE SOUTH 1/4 CORNER OF SECTION 28-18-11 AS HE DID NOT FIND THE STONE IN 1983. HE HAD FOUND THAT THE REMAINS OF A TREE ROW AND FENCE TO THE SOUTH TO BE AT OR NEAR THIS CORNER WERE APPROXIMATELY HALF WAY BETWEEN THE SOUTHWEST AND THE SOUTHEAST CORNERS AS RE-ESTABLISHED. THE NORTH-SOUTH POSITION OF THIS CORNER WAS DEEMED **LOST** AS THE ONLY PHYSICAL EVIDENCE CONSISTS OF A CROP LINE. HE DID **NOT** REESTABLISH THE SOUTH 1/4 CORNER OF SECTION 28-18-11 ON THIS SURVEY.

NORTH QUARTER CORNER 33-18-11