

**NORTH 1/4 CORNER SECTION 05, TOWNSHIP 18 SOUTH, RANGE 12 EAST**

- 1) ON PAGE 75 OF THE GLO ORIGINAL FIELD NOTES IN THE DRAFTING ROOM IN THE COUNTY ENGINEER'S OFFICE IT STATES THAT **THEY SET A LIMESTONE 19" X 10" X 3"** FOR THE NORTH 1/4 CORNER OF SECTION 5-18-12 ON THE TOWNSHIP LINE DECEMBER 14, 1856.

THE GOVERNMENT SURVEY NOTES SHOWS THE FOLLOWING INFORMATION:

- 1) 40.00 CHAINS WEST ON THE TOWNSHIP LINE TO THE 15" X 12" X 4" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 5 & 6-18-12
- 2) 40.00 CHAINS EAST ON THE TOWNSHIP LINE TO THE 19" X 10" X 4" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 4 & 5-18-12

- 2) SIEGMUND H. MEIER, L.S. 256, IN A LAND SURVEY REFERENCE REPORT DATED APRIL 1990, SURVEY F32001 IN THE SURVEY FILE FOR TOWNSHIP 17-12 FOR A 7.882 ACRE TRACT IN THE SOUTHEAST 1/4 OF SECTION 32-17-12, SAID THAT HE DUG FOR THE STONE AT THE SOUTH 1/4 CORNER OF SECTION 32-17-12 ON THE TOWNSHIP LINE AT THE INTERSECTION OF FENCE LINES AND THE TRAVELED WAY OF THE ROAD, AND HE FOUND NOTHING. HE DUG AGAIN THE NEXT DAY 10' EAST OF THIS LOCATION AND HE FOUND NOTHING. HE MET WITH AN OPERATOR FROM THE LYON COUNTY ROAD DEPARTMENT AND HE USED A MOTOR GRADER AND EXCAVATED A HOLE FROM 3' WEST OF THE FENCE INTERSECTION TO 20' EAST OF THE FENCE INTERSECTION LONG AND APPROXIMATELY 12' WIDE; AND NO EVIDENCE OF THE CORNER WAS FOUND. HE DEEMED THAT THIS CORNER WAS **OBLITERATED. HE SET A 1/2" X 24" REBAR WITH HIS ALUMINUM CAP AT 6" BELOW THE ROAD SURFACE** FOR THE SOUTH 1/4 CORNER OF SECTION 32-17-12 BASED ON PHYSICAL EVIDENCE THAT HE FOUND AT THIS CORNER: I.E., ROAD RECORDS, FENCE LINES AND MEASUREMENTS FROM THE SOUTHEAST CORNER OF SECTION 32-17-12 AND THE ROAD INTERSECTION AT THE SOUTHWEST CORNER OF SECTION 32-17-12.

- 1) 22.2' NORTH TO A SPIKE & WASHER IN THE TOP OF A CORNER FENCE POST
- 2) 23.2' SOUTH TO A SPIKE & 2 WASHERS IN THE TOP OF A CORNER FENCE POST
- 3) FENCE BEARS NORTH ON LINE
- 4) FENCE BEARS SOUTH ON LINE
- 5) CENTERLINE TRAVELED WAY OF THE ROAD BEARS EAST-WEST ON LINE

HIS SURVEY DRAWING SHOWS THE FOLLOWING INFORMATION:

- 1) 1,626.73' EAST ON THE TOWNSHIP LINE TO THE 1/2" REBAR HE SET FOR THE SOUTHWEST CORNER OF THE 7.882 ACRE TRACT
- 2) 2,147.73' EAST ON THE TOWNSHIP LINE TO THE 1/2" REBAR HE SET FOR THE SOUTHEAST CORNER OF THE 7.882 ACRE TRACT
- 3) 2,649.73' EAST ON THE TOWNSHIP LINE TO THE 1/2" REBAR HE FOUND AT THE SOUTHEAST CORNER OF SECTION 32-17-12

- 3) WARREN CHIP WOODS, L.S. 603, COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED SEPTEMBER 01, 2006, FOR PROJECT NUMBER 06-LA, **FOUND THE 1/2" REBAR AT 0.3' BELOW THE GRAVEL ROAD SURFACE** AT THE NORTH 1/4 CORNER OF SECTION 5-18-12 ON THE TOWNSHIP LINE FROM EXISTING REFERENCE TIES ON FILE AT THE COUNTY ENGINEER'S OFFICE BY SIGMUND H. MEIER, L.S. 256, WHO SET THIS REBAR IN 1990. THE ALUMINUM CAP FROM SIEGMUND H. MEIER WAS MISSING.

- 1) 22.9' NORTH TO A SPIKE & WASHER IN THE TOP OF A CORNER FENCE POST
- 2) 23.15' SOUTH TO A MAG NAIL & WASHER IN THE EAST FACE OF A CORNER FENCE POST
- 3) 23.25' SW TO A MAG NAIL & WASHER IN THE EAST FACE OF A POWER POLE
- 4) A FENCE BEARS NORTH ON LINE
- 5) 3' EAST TO A LINE OF OLD FENCE TO THE SOUTH

MY TIES ARE CONTINUED ON PAGE 2

- 6) 2' NORTH TO THE CENTERLINE TRAVELED WAY OF GRAVEL COUNTY ROAD 250 EAST-WEST
  
- 4) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED JUNE 29, 2007 FOR PROJECT NUMBER 05357-02, SAID THAT **HE FOUND THE 1/2" REBAR** AT THE NORTH 1/4 CORNER OF SECTION 5-18-12 ON THE TOWNSHIP LINE FROM EXISTING REFERENCE TIES ON FILE AT THE COUNTY ENGINEER'S OFFICE.
  - 1) 23.2' SOUTH TO A MAG NAIL & WASHER IN A CORNER FENCE POST
  - 2) 22.9' NORTH TO A SPIKE & WASHER IN THE TOP OF A CORNER FENCE POST
  - 3) 23.25' SW TO A MAG NAIL & WASHER IN A POWER POLE
  - 4) IN LINE WITH A FENCE TO THE NORTH
  - 5) 3.0' EAST TO AN OLD FENCE LINE TO THE SOUTH
  - 6) 2.0' NORTH TO THE TRAVELED WAY OF THE GRAVEL ROAD EAST-WEST
  
- 5) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED JANUARY 13, 2012 FOR PROJECT NUMBER 12004-02, SURVEY F05001 IN THE SURVEY FILE FOR TOWNSHIP 18-12 FOR AN 11.03 ACRE TRACT IN THE NORTHEAST 1/4 OF SECTION 5 FOR JIM RICHARDSON, SAID THAT **HE FOUND A 1/2" REBAR AT 8" DEEP** AT THE NORTH 1/4 CORNER OF SECTION 5-18-12 ON THE TOWNSHIP LINE FROM HIS EXISTING REFERENCE TIES ON FILE IN THE COUNTY ENGINEER'S OFFICE DATED JUNE 2007.
  - 1) 23.30' SOUTH TO A MAG NAIL & WASHER IN A CORNER FENCE POST
  - 2) 22.90' NORTH TO A SPIKE & WASHER IN THE TOP OF A CORNER FENCE POST
  - 3) 23.25' SSW TO A MAG NAIL & WASHER IN A POWER POLE
  - 4) IN LINE WITH A FENCE TO THE NORTH
  - 5) 2.0' NORTH TO THE CENTERLINE TRAVELED WAY OF COUNTY ROAD 250 EAST-WEST

HIS SURVEY DRAWING SHOWS THE FOLLOWING INFORMATION:

  - 1) 338.00' EAST ON THE TOWNSHIP LINE TO THE NORTHEAST CORNER OF THE 11.03 ACRE TRACT, AS WITNESSED BY THE 1/2" REBAR WITH HIS "LS 752" CAP HE SET AT 20.00' SOUTH
  - 2) 2,650.50' EAST ON THE TOWNSHIP LINE TO THE 1/2" IRON BAR HE FOUND AT THE NORTHEAST CORNER OF THE NE1/4 OF SECTION 5-18-12
  - 3) 1,243.00' SOUTH TO THE 1/2" IRON BAR WITH HIS "LS 752" CAP HE FOUND AT THE SOUTHWEST CORNER OF THE 11.03 ACRE TRACT

NORTH QUARTER CORNER 05-18-12