

NORTHWEST CORNER SECTION 04, TOWNSHIP 21 SOUTH, RANGE 10 EAST

- 1) ON PAGE 264 OF THE GLO ORIGINAL FIELD NOTES IN THE DRAFTING ROOM IN THE COUNTY ENGINEER'S OFFICE IT STATES THAT THEY INTERSECTED THE 4TH STANDARD PARALLEL SOUTH AT 7.58 CHAINS WEST OF THE CORNER TO SECTIONS 32 & 33-20-10 AND 32.42 CHAINS EAST OF THE 1/4 CORNER. **THEY SET A LIMESTONE 22" X 15" X 3"** FOR THE CORNER TO SECTIONS 4 & 5-21-10 ON THE 4TH STANDARD PARALLEL ON JUNE 8, 1857.
THE GOVERNMENT SURVEY NOTES SHOW THE FOLLOWING INFORMATION:
 - 1) 42.88 CHAINS SOUTH TO THE 22" X 14" X 3" LIMESTONE THEY SET FOR THE 1/4 CORNER BETWEEN SECTIONS 4 & 5-21-10
 - 2) 82.88 CHAINS SOUTH TO THE 23" X 11" X 3" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 4, 5, 8 & 9-21-10

- 2) COMMISSIONER'S ROAD JOURNAL BOOK "B", PAGE 120
ON OCTOBER 27, 1959, A PETITION SIGNED BY C. G. KARR AND OTHERS FOR THE **VACATION** OF A ROAD IN TOWNSHIP 16-11 WAS PRESENTED TO W. A. STOLFUS, COUNTY CLERK. THE ROAD WAS VIEWED BY THE COUNTY COMMISSIONERS AND W. D. KRETSINGER, COUNTY ENGINEER, ON OCTOBER 22, 1959 AND THE FINAL ORDER WAS NOT DATED BUT SIGNED BY ALL THREE MEMBERS OF THE BOARD OF COUNTY COMMISSIONERS **VACATING** THE FOLLOWING ROAD:
 - 1) BEGINNING AT THE NORTHEAST CORNER OF SECTION 4-21-10, THENCE WEST TWO (2) MILES TO THE NORTHWEST CORNER OF SECTION 5-21-10 AND THERE ENDING.
 - 2) NOW THEREFORE BE IT RESOLVED, THAT IN THE JUDGMENT OF SAID BOARD OF COUNTY COMMISSIONERS THE ROAD HEREINAFTER DESCRIBED IS NOT A PUBLIC UTILITY BY REASON OF NEGLECT, NONUSE AND INCONVENIENCE
 - 3) BE IT FURTHER RESOLVED, IT IS HEREBY ORDERED THAT THE ABOVE DESCRIBED ROAD IS HEREBY **VACATED.**

NORTHWEST CORNER 04-21-10