

**NORTH 1/4 CORNER SECTION 25, TOWNSHIP 21 SOUTH, RANGE 11 EAST**

- 1) ON PAGE 407 OF THE GLO ORIGINAL FIELD NOTES IN THE DRAFTING ROOM IN THE COUNTY ENGINEER'S OFFICE IT STATES THAT **THEY SET A LIMESTONE 20" X 10" X 3"** FOR THE 1/4 CORNER BETWEEN SECTIONS 24 & 25-21-11.  
THE GOVERNMENT SURVEY NOTES SHOW THE FOLLOWING INFORMATION:
  - 1) 39.79 CHAINS WEST TO THE 18" X 16" X 5" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 23, 24, 25 & 26-21-11
  - 2) 39.79 CHAINS EAST TO THE 16" X 13" X 4" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 24 & 25-21-11 ON THE EAST TOWNSHIP BOUNDARY
  
- 2) STEVEN S. BROSEMER, L.S. 752, IN A LAND SURVEY REFERENCE REPORT DATED NOVEMBER 14, 1983, SAID THAT HE CONSIDERED THAT THE NORTH 1/4 CORNER OF SECTION 25-21-11 WAS **OBLITERATED**. **HE SET A 5/8" X 24" REBAR WITH A YELLOW PLASTIC CAP** FOR THE NORTH 1/4 CORNER OF SECTION 25-21-11 BASED ON THE PHYSICAL EVIDENCE THAT HE FOUND AT THIS CORNER; I.E., IN LINE WITH FENCES NORTH AND SOUTH AND IN THE CENTER OF THE ROAD RIGHT-OF-WAY.
  - 1) 25.0' NORTH AND SOUTH TO A LINE OF FENCE TO THE EAST & WEST
  - 2) IN LINE WITH FENCES TO THE NORTH & SOUTH
  - 3) 2,631.0'± MORE OR LESS EAST TO THE NORTHEAST CORNER OF SECTION 25-21-11 ON THE RANGE LINE

NORTH QUARTER CORNER 25-21-11