

**NORTH 1/4 CORNER SECTION 22, TOWNSHIP 21 SOUTH, RANGE 13 EAST**

- 1) ON PAGE 688 OF THE GLO ORIGINAL FIELD NOTES IN THE DRAFTING ROOM IN THE COUNTY ENGINEER'S OFFICE IT STATES THAT **THEY SET A LIMESTONE 24" X 14" X 3"** FOR THE 1/4 CORNER BETWEEN SECTIONS 15 & 22-21-13 ON JUNE 7, 1856.  
THE GOVERNMENT SURVEY NOTES SHOW THE FOLLOWING INFORMATION:
  - 1) 40.20 CHAINS WEST TO THE 27" X 16" X 3" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 15, 16, 21 & 22-21-13
  - 2) 40.20 CHAINS EAST TO THE 25" X 15" X 3" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 14, 15, 22 & 23-21-13 ON THE COUNTY LINE
  
- 2) R. H. EDMISTON, COUNTY SURVEYOR FROM 1884 TO 1887, IN SURVEY NUMBER 46, A **PERMANENT SURVEY** RECORDED IN SURVEY BOOK "E" ON PAGE 46 DATED JUNE 30 TO JULY 1, 1884 AT THE REQUEST OF MRS. AMY BRAUCHER AND FRED BRAUCHER TO ESTABLISH THE NORTHWEST CORNER AND TEST THE NORTHEAST CORNER OF SECTION 22-21-13 ON THE LYON AND COFFEY COUNTY LINE, SHOWS ON HIS SURVEY DRAWING THAT **HE FOUND THE STONE** AT THE NORTH 1/4 CORNER OF SECTION 22-21-13 ON THIS **PERMANENT SURVEY**.
  
- 3) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED FEBRUARY 25, 2002, FOR PROJECT NUMBER 02060-02, SURVEY F22002 IN THE SURVEY FILE FOR TOWNSHIP 21-13 FOR A SURVEY OF THE NORTH LINE OF THE NORTHWEST QUARTER OF SECTION 22-21-13 FOR THE LYON COUNTY ROAD & BRIDGE DEPARTMENT FOR BRIDGE REPLACEMENT PROJECT 02-89, SAID THAT HE CONSIDERED THAT THE NORTH 1/4 CORNER OF SECTION 22-21-13 WAS **OBLITERATED**. **HE SET A 5/8" X 24" REBAR WITH A LYON COUNTY CAP** FOR THE NORTH 1/4 CORNER OF SECTION 22-21-13 BASED ON THE PHYSICAL EVIDENCE THAT HE FOUND AT THIS CORNER; I.E., IN LINE WITH THE HEDGE AND THE FENCE TO THE SOUTH, AND 20' NORTH OF THE SOUTH RIGHT-OF-WAY FENCE. HE SAID THAT THIS CORNER SHOWS EVIDENCE OF A GLO ERROR OR FRAUD. THIS SURVEY WAS FILED IN VOLUME 547 ON PGE 593 IN THE REGISTER OF DEEDS OFFICE ON APRIL 15, 2002.
  - 1) 26.65' SW TO A CONCRETE NAIL & WASHER IN A FENCE/GATE POST
  - 2) 20.2' SOUTH TO A CONCRETE NAIL & WASHER IN A CORNER FENCE POST
  - 3) 33.0' SE TO A CONCRETE NAIL & WASHER IN A FENCE/GATE POST
  - 4) 20.0' SOUTH TO A FENCE LINE EAST-WEST
  - 5) IN LINE WITH A FENCE AND A HEDGE TO THE SOUTH
  - 6) IN THE CENTERLINE TRAVELED WAY OF GRAVEL COUNTY ROAD 40 EAST-WESTHIS SURVEY DRAWING SHOWS THE FOLLOWING INFORMATION:
  - 1) 850.90' WEST TO THE 1/2" REBAR WITH HIS "LS 752" CAP HE SET FOR A P.O.T.
  - 2) 1,125.07' WEST TO THE 1/2" REBAR WITH HIS "LS 752" CAP HE SET FOR A P.O.T.
  - 3) 1,425.07' WEST TO THE 1/2" REBAR WITH HIS "LS 752" CAP HE SET FOR A P.O.T.
  - 4) 2,625.07' WEST TO THE STONE HE FOUND AT THE NORTHWEST CORNER OF SECTION 22-21-13, WITH 5/8" REBARS WITH LYON COUNTY CAPS HE SET ON THE EAST AND WEST SIDES AND FLUSH WITH THE STONE
  - 5) 2,692.30' EAST TO THE 5/8" REBAR WITH A LYON COUNTY CAP IN A MONUMENT WELL HE FOUND AT THE NORTHEAST CORNER OF SECTION 22-21-13 ON THE LYON AND COFFEY COUNTY LINE

NORTH QUARTER CORNER 22-21-13