

NORTH 1/4 CORNER SECTION 36, TOWNSHIP 16 SOUTH, RANGE 11 EAST

- 1) ON PAGE 285 OF THE GLO ORIGINAL FIELD NOTES IN THE DRAFTING ROOM IN THE COUNTY ENGINEER'S OFFICE IT STATES THAT **THEY SET A LIMESTONE 14" X 9" X 7"** FOR THE 1/4 CORNER BETWEEN SECTIONS 35 & 36-16-11.
THE GOVERNMENT SURVEY NOTES SHOWS THE FOLLOWING INFORMATION:
 - 1) 40.06 CHAINS WEST TO THE 24" X 11" X 6" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 25, 26, 35 & 36-16-11
 - 2) 40.06 CHAINS EAST TO THE 18" X 12" X 5" LIMESTONE THEY SET FOR THE CORNER OF SECTIONS 35 & 36-16-11 ON THE EAST TOWNSHIP BOUNDARY

- 2) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED MARCH 21, 1990, FOR JOB NUMBER 90055, SAID THAT **HE SET A 1/2" X 24" REBAR WITH HIS "LS 752" CAP** FOR THE SOUTH 1/4 CORNER OF SECTION 25-16-11. THE *REPORT OF SURVEY* INCLUDED IN SURVEY F25001 IN THE SURVEY FILES FOR TOWNSHIP 16-11 STATED THAT HE EXCAVATED FOR THE GLO STONE AT THE SOUTH 1/4 CORNER OF SECTION 25-16-11 BUT HE DID **NOT** FIND THE STONE.
 - 1) 29.4' SSW TO A NAIL & WASHER IN A CORNER FENCE POST
 - 2) 36.6' NE TO A NAIL & WASHER IN A FENCE POST
 - 3) 28.5' NORTH TO A NAIL & WASHER IN A FENCE POST
 - 4) 38.35' NW TO A NAIL & WASHER IN A FENCE POST
 - 5) IN LINE WITH A HEDGE TO THE SOUTH
 - 6) 3.0' NORTH TO THE CENTERLINE TRAVELED WAY OF THE ROAD EAST-WEST
 - 7) IN LINE WITH A FENCE TO THE NORTH

- 3) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED FEBRUARY 12, 2008, FOR PROJECT NUMBER 07415-02, SURVEY F36001 IN THE SURVEY FILE FOR TOWNSHIP 16-11, FOR A SURVEY OF TWO TRACTS IN THE SOUTHWEST 1/4 OF SECTION 36-16-11 FOR MARK & TAMMY DENTON, SAID THAT **HE FOUND THE 1/2" REBAR WITH HIS "LS 752" CAP** AT THE NORTH 1/4 CORNER OF SECTION 36-16-11 FROM HIS EXISTING REFERENCES ON FILE IN THE COUNTY ENGINEER'S OFFICE DATED MARCH 1990.
 - 1) 27.20' SOUTH TO A CONCRETE NAIL & WASHER IN A CORNER FENCE POST
 - 2) 36.30' NE TO A CONCRETE NAIL & WASHER IN A FENCE POST
 - 3) 28.30' NORTH TO A CONCRETE NAIL & WASHER IN A FENCE POST
 - 4) 37.45' NW TO A CONCRETE NAIL & WASHER IN THE TOP OF THE BRACE POST FOR A GATE
 - 5) IN LINE WITH A HEDGE ROW TO THE SOUTH
 - 6) IN LINE WITH A FENCE TO THE SOUTH
 - 7) 3.00' NORTH TO THE CENTERLINE TRAVELED WAY OF COUNTY ROAD 320 EAST-WESTHIS SURVEY DRAWING SHOWS THE FOLLOWING INFORMATION:
 - 1) 2,620.98' WEST TO THE 5/8" REBAR THROUGH THE STONE HE FOUND AT THE NORTHWEST CORNER OF THE NW1/4 OF SECTION 36-16-11
 - 2) 2,648.38' EAST TO THE 3/4" REBAR HE FOUND AT THE NORTHEAST CORNER OF THE NORTHEAST 1/4 OF SECTION 36-16-11
 - 3) 2,657.59' SOUTH TO THE 5/8" REBAR WITH A LYON COUNTY CAP HE SET FOR THE NORTHEAST CORNER OF THE SW1/4 OF SECTION 36-16-11
 - 4) 5,308.09' SOUTH TO THE 5/8" REBAR WITH A LYON COUNTY CAP HE SET FOR THE SOUTHEAST CORNER OF THE SW1/4 OF SECTION 36-16-11 ON THE TOWNSHIP LINE

NORTH QUARTER CORNER SECTION 36-16-11