

**CENTER CORNER SECTION 07, TOWNSHIP 16 SOUTH, RANGE 12 EAST**

- 1) **REA PIN—MUST VERIFY AND CHECK FOR OTHER MONUMENT BEFORE USING; IT WAS PROBABLY JUST “HEELED-IN” FOR UTILITY USE ONLY.** REA BOOK 30 ON PAGE 51 SAYS THAT **THEY SET AN IRON PIN AT THE CENTER CORNER OF SECTION 7-16-12 AT 2640 FEET WEST OF THE EAST 1/4 CORNER OF SECTION 7-16-12 IN A “PILE OF STONE”.**
  - 1) 30’ EAST TO A LOCUST TREE
  - 2) 48’ SE TO A BOX ELDER TREE
  
- 2) KRETSINGER REFERENCE TIE BOOKS FOR TOWNSHIP 16-12 SHOWS A **REA PIN AT THE “SW CORNER NE1/4 SECTION 07-16-12”.** **VERIFY BEFORE USING!! WARREN CHIP WOODS, L.S. 603, COUNTY SURVEYOR**
  - 1) 48’ SE TO A WITNESS [REA]
  - 2) 30’ EAST TO A WITNESS [REA]
  
- 3) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN SURVEY F07001 IN THE SURVEY FILE FOR TOWNSHIP 16-12 DATED SEPTEMBER 9, 1986 FOR PROJECT NUMBER 86084 AND RECORDED IN VOLUME 429 ON PAGE 121 IN THE REGISTER OF DEEDS OFFICE ON DECEMBER 3, 1986, SAID THAT THIS SECTION SHOWS EVIDENCE OF GLO FRAUD, AS THE DISTANCES EAST & WEST AND THE ALIGNMENT ALONG THE EAST SIDE ARE NOT IN HARMONY WITH THE GOVERNMENT NOTES. HE SAID THAT **HE SET A 1/2” X 24” REBAR WITH HIS “LS 752” CAP FOR THE CENTER CORNER OF SECTION 7-16-12 AT THE INTERSECTION OF THE LINES FROM THE OPPOSITE 1/4 CORNERS.**

HIS SURVEY DRAWING SHOWS THE FOLLOWING INFORMATION:

  - 1) 2,638.50’ NORTH TO THE STONE HE FOUND AT THE NORTH 1/4 CORNER OF SECTION 7-16-12
  - 2) 1,314.10’ SOUTH TO THE 1/2" REBAR WITH HIS “LS 752” CAP HE SET FOR THE WEST 1/16<sup>TH</sup> CORNER OF THE SE1/4 OF SECTION 7-16-12
  - 3) 2,628.19’ SOUTH TO THE 1/2" REBAR WITH HIS “LS 752” CAP HE SET FOR THE SOUTH 1/4 CORNER OF SECTION 7-16-12
  - 4) 1,313.09’ EAST TO THE THEORETICAL POSITION FOR THE NORTH 1/16<sup>TH</sup> CORNER OF THE SE1/4 OF SECTION 7-16-12
  - 5) 2,626.19’ EAST TO THE 1/2" REBAR WITH HIS “LS 752” CAP HE SET FOR THE EAST 1/4 CORNER OF SECTION 7-16-12

CENTER CORNER 07-16-12