

**WEST 1/4 CORNER SECTION 12, TOWNSHIP 16 SOUTH, RANGE 12 EAST**

- 1) ON PAGE 450 OF THE GLO ORIGINAL FIELD NOTES IN THE DRAFTING ROOM IN THE COUNTY ENGINEER'S OFFICE IT STATES THAT **THEY SET A LIMESTONE 18" X 10" X 8"** FOR THE 1/4 CORNER BETWEEN SECTIONS 11 & 12-16-12.
  
- 2) JAMES H. BROSEMER, L.S. 82, IN A LAND SURVEY REFERENCE REPORT DATED MAY 16, 1995, FOR A SURVEY FOR MELVIN STANFORD, SURVEY F11001 IN THE SURVEY FILE FOR TOWNSHIP 16-12, AND RECORDED IN VOLUME 491 ON PAGE 301 IN THE REGISTER OF DEEDS OFFICE ON JUNE 7, 1995, TO DETERMINE THE ACREAGE THAT LIES SOUTH OF THE RECENTLY CONSTRUCTED FENCE FROM THE EAST 1/4 CORNER OF SECTION 11 WEST TO THE WEST LINE OF SECTION 11 THAT LIES NORTH OF THE NORTH LINE OF THE SOUTH 1/2 OF THE SOUTHEAST 1/4 AND THE SOUTH 1/2 OF THE SOUTHWEST 1/4 OF SECTION 11, SAID THAT HE FOUND THAT THE EAST 1/4 CORNER OF SECTION 11-16-12 FALLS IN A 5' ROAD CUT, AND HE CONSIDERED THAT THE STONE WAS **DESTROYED**. **HE SET A 1/2" X 24" REBAR WITH HIS "LS 82" CAP** FOR THE EAST 1/4 CORNER OF SECTION 11-16-12 IN LINE WITH THE FENCES TO THE EAST AND WEST, AND AT A SPLIT OF THE ROAD FENCES.
  - 1) IN LINE WITH FENCES TO THE EAST AND WEST
  - 2) 27.5' EAST TO A CORNER FENCE POST
  - 3) 27.5' WEST TO A CORNER FENCE POST
  
- 3) JAMES H. BROSEMER, L.S. 82, IN A LAND SURVEY REFERENCE REPORT DATED MAY 16, 1995, FOR A SURVEY FOR MELVIN STANFORD RECORDED IN VOLUME 491 ON PAGE 300 IN THE REGISTER OF DEEDS OFFICE ON JUNE 7, 1995, SURVEY F11002 IN THE SURVEY FILE FOR TOWNSHIP 16-12, SAID THAT **HE FOUND THE 1/2" REBAR WITH HIS "LS 82" CAP** AT THE EAST 1/4 CORNER OF SECTION 11-16-12.
  - 1) IN LINE WITH THE FENCES TO THE EAST AND WEST
  - 2) 27.5' EAST TO A CORNER FENCE POST
  - 3) 27.5' WEST TO A CORNER FENCE POST

HIS SURVEY DRAWING SHOWS THE FOLLOWING INFORMATION:

  - 1) 2,642.53' WEST TO THE CALCULATED POSITION FOR THE NORTHWEST CORNER OF THE SE1/4 OF SECTION 11-16-12
  - 2) 1,314.94' SOUTH TO THE CALCULATED POSITION FOR THE EAST 1/16<sup>TH</sup> CORNER OF THE SE1/4 OF SECTION 11-16-12
  - 3) 2,629.88' SOUTH TO THE 1/2" REBAR WITH HIS "LS 82" CAP HE SET FOR THE SOUTHEAST CORNER OF SECTION 11-16-12
  
- 4) JAMES H. BROSEMER, L.S. 82, IN A LAND SURVEY REFERENCE REPORT DATED MAY 16, 1995, FOR THE SURVEY FOR MELVIN STANFORD FOR TWO TRACTS IN THE NORTHEAST 1/4 OF SECTION 11 RECORDED IN VOLUME 491 ON PAGE 299 IN THE REGISTER OF DEEDS OFFICE ON JUNE 7, 1995, SURVEY F11003 IN THE SURVEY FILE FOR TOWNSHIP 16-12, SAID THAT **HE FOUND THE 1/2" X 24" REBAR WITH HIS "LS 82" CAP** AT THE EAST 1/4 CORNER OF SECTION 11-16-12 FROM HIS SURVEY LISTED ABOVE.
  - 1) IN LINE WITH FENCES TO THE EAST AND WEST
  - 2) 27.5' EAST TO A CORNER FENCE POST
  - 3) 27.5' WEST TO A CORNER FENCE POST

HIS SURVEY DRAWING SHOWS THE FOLLOWING INFORMATION:

  - 1) 2,642.53' WEST TO THE CALCULATED POSITION FOR THE SOUTHWEST CORNER OF THE NE1/4 OF SECTION 11-16-12
  - 2) 2,634.06' NORTH TO THE 1/2" REBAR WITH HIS "LS 82" CAP HE SET FOR THE NORTHEAST CORNER OF SECTION 11-16-12

WEST QUARTER CORNER 12-16-12