

WEST 1/16TH CORNER OF THE SOUTHEAST QUARTER OF SECTION 23, TOWNSHIP 18 SOUTH, RANGE 11 EAST

- 1) ROBERT MILLIKEN, COUNTY SURVEYOR FROM 1870 TO 1875 AND FROM 1882 TO 1883, IN A **PERMANENT SURVEY** RECORDED IN SURVEY BOOK "C" ON PAGE 59 DATED FEBRUARY 18, 1874, TO SUBDIVIDE THE SOUTHWEST 1/4 OF SECTION 23-18-11 INTO EAST & WEST HALVES, SAID THAT **HE SET A STONE** FOR THE PERMANENT 1/2/4 CORNER ON THE EAST SIDE OF THE SOUTHWEST 1/4 OF SECTION 23-18-11 ON THIS **PERMANENT SURVEY**.
- 2) ALVA J. SMITH, COUNTY SURVEYOR FROM 1900 THROUGH 1906, IN SURVEY NUMBER 82, A **PERMANENT SURVEY** RECORDED IN SURVEY BOOK "F" ON PAGE 161 DATED AUGUST 11-25, 1903 AT THE REQUEST OF T. S. JONES FOR A SURVEY FOR THE PURPOSE OF LOCATING AND PERMANENTLY ESTABLISHING THE SOUTHEAST CORNER AND THE EAST 1/4 CORNER OF SECTION 22-18-11 AND RUN SUCH LINES AS MAY BE NECESSARY TO PROPERLY COMPLETE THE WORK, SHOWS ON HIS SURVEY DRAWING THAT **HE FOUND THE STONE** AT THE EAST 1/2/4 CORNER OF THE SOUTHWEST 1/4 OF SECTION 23-18-11 ON THIS **PERMANENT SURVEY**. HIS FIELD NOTES ARE IN HIS BOOK 3 ON PAGE 178 IN THE "KRETSINGER COLLECTION" OF FIELD BOOKS, AND THERE IS ADDITIONAL INFORMATION IN PACKET "M 73" IN MISCELLANEOUS DRAWER NUMBER 3 IN THE VAULT IN THE COUNTY ENGINEER'S OFFICE.
- 3) COMMISSIONER'S ROAD JOURNAL BOOK "B", PAGE 175
ON DECEMBER 11, 1979 A PETITION SIGNED BY JOHN S. MARKEY AND OTHERS FOR THE **VACATION** OF A ROAD IN TOWNSHIP 18-11 WAS PRESENTED TO PEGGY STICE, DEPUTY COUNTY CLERK. THE COUNTY COMMISSIONERS VIEWED THE ROAD ON JANUARY 3, 1980, AND THEIR FINAL ORDER DATED JANUARY 3, 1980 ORDERED THE FOLLOWING ROAD BE **VACATED AS PETITIONED**:
 - 1) BEGINNING 20 FEET EAST OF THE SOUTHWEST CORNER OF THE SOUTHEAST 1/4 OF SECTION 23-18-11; THENCE NORTH 1,320 FEET; THENCE WEST 40 FEET; THENCE SOUTH 1,320 FEET; THENCE EAST 40 FEET TO THE PLACE OF BEGINNING.
- 4) JOHN R. YOUNG, L.S. 112, IN SURVEY F23001 IN THE SURVEY FILE FOR TOWNSHIP 18-11 DATED NOVEMBER & DECEMBER 1977 FOR A *CERTIFICATE OF SURVEY* FOR THE NORTH HALF OF THE SOUTHWEST QUARTER OF SECTION 23-18-11, SAID THAT **HE SET A 1/2" REBAR** FOR THE SOUTHEAST CORNER OF THE NORTH 1/2 OF THE SOUTHWEST 1/4 OF SECTION 23-18-11 ON TRUE LINE AND HALFWAY BETWEEN THE CENTER CORNER AND THE SOUTH 1/4 CORNER OF SECTION 23-18-11.
 - 1) 6.8' ENE TO A SPIKE & WASHER IN A 20" TREE
 - 2) 25.3' NE TO A SPIKE & 2 WASHER IN A FENCE POST
 - 3) 30.2' TO A SPIKE & 3 WASHERS IN A 20" TREEHIS SURVEY DRAWING SHOWS THE FOLLOWING INFORMATION:
 - 1) 1,332.13' NORTH TO THE CENTER CORNER OF SECTION 23-18-11 AT A FENCE CORNER – HE DID NOT DESCRIBE WHAT HE SET FOR THE CENTER CORNER OR IF HE JUST USED THE FENCE CORNER
 - 2) 1,332.13' SOUTH TO THE 3/4" BAR HE FOUND AT THE SOUTH 1/4 CORNER OF SECTION 23-18-11
 - 3) 2,685.11' WEST TO THE 1/2" REBAR HE SET FOR THE SOUTHWEST CORNER OF THE N1/2 OF THE SW1/4 OF SECTION 23-18-11

WEST SIXTEENTH CORNER SOUTHEAST QUARTER 23-18-11