

WEST 1/4 CORNER SECTION 18, TOWNSHIP 20 SOUTH, RANGE 11 EAST

- 1) ON PAGE 40 OF THE GLO ORIGINAL FIELD NOTES IN THE DRAFTING ROOM IN THE COUNTY ENGINEER'S OFFICE IT STATES THAT **THEY SET A SANDSTONE 33" X 16" X 3-1/2"** FOR THE WEST 1/4 CORNER OF SECTION 18-20-11 ON THE WEST TOWNSHIP BOUNDARY ON NOVEMBER 25, 1856.

THE GOVERNMENT SURVEY NOTES SHOWS THE FOLLOWING INFORMATION:

- 1) 40.00 CHAINS NORTH ON THE WEST TOWNSHIP BOUNDARY TO THE 20" X 13" X 4" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 7 & 18-20-11
 - 2) 40.00 CHAINS SOUTH ON THE WEST TOWNSHIP BOUNDARY TO THE 23" X 17" X 2" LIMESTONE THEY SET FOR THE CORNER TO SECTIONS 18 & 19-20-11
- 2) MATTHEW BROWN, COUNTY SURVEYOR FROM 1888 TO 1900, AND 1914, BY C. P. COWEN, DEPUTY COUNTY SURVEYOR, IN SURVEY NUMBER 116, A **PERMANENT SURVEY** AT THE REQUEST OF GEORGE CRICKLAND TO ESTABLISH THE LINES AND CORNERS OF THE EAST 1/2 OF THE NORTHWEST 1/4 OF SECTION 6-20-11 RECORDED IN SURVEY BOOK "F" ON PAGE 132 DATED MAY 1-9, 1888, SAID THAT **HE FOUND THE 1/4 STONE BETWEEN SECTIONS 13-20-10 & 18-20-11 ON THE RANGE LINE ON THIS PERMANENT SURVEY.**

- 3) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED MARCH 4, 1997, FOR PROJECT NUMBER 97036-02 FOR THE LYON COUNTY ROAD & BRIDGE DEPARTMENT FOR BRIDGE REPLACEMENT PROJECT NUMBER 97-1S, SAID THAT **HE FOUND THE FRACTURED GLO STONE** AT THE WEST 1/4 CORNER OF SECTION 18-20-11 ON THE RANGE LINE. HE IDENTIFIED THIS STONE AS THE STONE THAT WAS FOUND BY COUNTY SURVEYOR MATTHEW BROWN IN 1888. **HE SET A 5/8" REBAR WITH A LYON COUNTY CAP** WHERE THE FRACTURED STONE WAS FOUND.

- 1) 17.60' WEST TO A CONCRETE NAIL IN A FENCE POST
- 2) 44.60' SW TO A CONCRETE NAIL IN A FENCE POST
- 3) 152.30' SE TO THE TOP CENTER OF A TELEPHONE PEDESTAL
- 4) 3.0' WEST TO THE TRAVELED WAY OF THE GRAVEL ROAD NORTH-SOUTH

HIS DRAWING ON HIS REFERENCE REPORT SHOWS THE FOLLOWING:

- 1) 2,632.55' SOUTH ON THE RANGE LINE TO THE SOUTHWEST CORNER OF SECTION 18-20-11
 - 2) 5,265.10' SOUTH ON THE RANGE LINE TO THE WEST 1/4 CORNER OF SECTION 19-20-11
 - 3) 7,897.65' SOUTH ON THE RANGE LINE TO THE SOUTHWEST CORNER OF SECTION 19-20-11
- 4) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED NOVEMBER 10, 2006, FOR PROJECT NUMBER 06293-02, SURVEY F18001 IN THE SURVEY FILE FOR TOWNSHIP 20-11 FOR THE LYON COUNTY ROAD & BRIDGE DEPARTMENT FOR LYON COUNTY PROJECT NUMBER 06-KU, THE REPLACEMENT OF BRIDGE 957.5-532.0, SAID THAT **HE FOUND THE 5/8" X 24" REBAR WITH A LYON COUNTY CAP AT THE LOCATION WHERE HE FOUND THE FRACTURED GLO STONE IN 1997** AT THE WEST 1/4 CORNER OF SECTION 18-20-11 ON THE RANGE LINE FROM HIS EXISTING REFERENCE TIES ON FILE AT THE COUNTY ENGINEER'S OFFICE DATED MARCH 1997.

- 1) 17.75' WEST TO A 40 D SPIKE & WASHER IN A FENCE POST
- 2) 31.75' SW TO A 40 D SPIKE & WASHER IN A FENCE POST
- 3) 152.30' SE TO THE TOP CENTER OF A TELEPHONE PEDESTAL
- 4) 3.0' EAST TO THE CENTERLINE TRAVELED-WAY FOR COUNTY ROAD "G"
- 5) IN LINE WITH A FENCE TO THE WEST EXTENDED

HIS SURVEY DRAWING SHOWS THE FOLLOWING INFORMATION:

HIS INFORMATION IS CONTINUED ON PAGE 2

- 1) 2,632.46' SOUTH ON THE RANGE LINE TO THE 5/8" REBAR WITH A LYON COUNTY CAP HE FOUND AT THE SOUTHWEST CORNER OF SECTION 18-20-11
 - 2) 2,634.51' NORTH ON THE RANGE LINE TO THE 5/8" REBAR WITH A LYON COUNTY CAP HE SET FOR THE NORTHWEST CORNER OF SECTION 18-20-11 AND PROJECT STATION 0+00.00
 - 3) 5,269.02' NORTH ON THE RANGE LINE TO THE 5/8" REBAR WITH A LYON COUNTY CAP HE SET FOR THE WEST 1/4 CORNER OF SECTION 7-20-11
- 5) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED DECEMBER 9, 2008 FOR PROJECT NUMBER 08278-02, SURVEY F18002 IN THE SURVEY FILE FOR TOWNSHIP 20-11 FOR A SURVEY OF THE NORTHWEST QUARTER OF THE NORTHWEST QUARTER OF SECTION 18-20-11 FOR DONNA WILLIAMS, SAID THAT **HE FOUND THE 5/8" REBAR WITH A LYON COUNTY CAP AT THE LOCATION WHERE HE FOUND THE FRACTURED GLO STONE IN 1997** AT THE WEST 1/4 CORNER OF SECTION 18-20-11 ON THE RANGE LINE FROM HIS EXISTING REFERENCES ON FILE IN THE COUNTY ENGINEER'S OFFICE DATED NOVEMBER 2006.
- 1) 17.75' WEST TO A 40 D NAIL & WASHER IN A FENCE POST
 - 2) 31.55' SW TO A 40 D SPIKE & WASHER IN A FENCE POST
 - 3) 152.30' SE TO THE TOP CENTER OF A TELEPHONE PEDESTAL
 - 4) IN THE CENTERLINE TRAVELED WAY OF COUNTY ROAD "G"
- HIS DRAWING SHOWS THE FOLLOWING INFORMATION:**
- 1) 2,632.54' SOUTH ON THE RANGE LINE TO THE 5/8" REBAR WITH A LYON COUNTY CAP HE FOUND AT THE SOUTHWEST CORNER OF SECTION 18-20-11
 - 2) 1,317.21' NORTH ON THE RANGE LINE TO THE 1/2" REBAR WITH HIS "LS 752" CAP HE SET FOR THE SOUTHWEST CORNER OF THE NW1/4 OF THE NW1/4 OF SECTION 18-20-11
 - 3) 2,634.42' NORTH ON THE RANGE LINE TO THE 5/8" REBAR WITH A LYON COUNTY CAP HE FOUND AT THE NORTHWEST CORNER OF SECTION 18-20-11
 - 4) 1,324.26' EAST TO THE THEORETICAL POSITION FOR THE SOUTHWEST CORNER OF THE SE1/4 OF THE NW1/4 OF SECTION 18-20-11
 - 5) 2,642.27' EAST TO THE THEORETICAL POSITION FOR THE CENTER CORNER OF SECTION 18-10-111
 - 6) 5,278.48' EAST TO THE 5/8" REBAR WITH A LYON COUNTY CAP HE FOUND AT THE EAST 1/4 CORNER OF SECTION 18-20-11

WEST QUARTER CORNER 18-20-11