

WEST 1/4 CORNER SECTION 23, TOWNSHIP 20 SOUTH, RANGE 11 EAST

- 1) ON PAGE 389 OF THE GLO ORIGINAL FIELD NOTES IN THE DRAFTING ROOM IN THE COUNTY ENGINEER'S OFFICE IT STATES THAT **THEY SET A LIMESTONE 18" X 14" X 3"** FOR THE 1/4 CORNER BETWEEN SECTIONS 22 & 23-20-11.

- 2) SAMUEL P. DAVIES, DEPUTY COUNTY SURVEYOR, IN SURVEY NUMBER 65, A **PERMANENT SURVEY** RECORDED IN SURVEY BOOK "B" ON PAGE 63 DATED AUGUST 6, 1870 TO ESTABLISH QUARTER QUARTER CORNERS OF THE NORTHEAST 1/4 OF SECTION 22-20-11, SAID THAT **HE FOUND THE STONE** AT THE EAST 1/4 CORNER OF SECTION 22-20-11 ON THIS **PERMANENT SURVEY**.
HIS SURVEY NOTES SHOWS THE FOLLOWING INFORMATION:
 - 1) 19.92-1/2 CHAINS NORTH TO THE POST THAT HE SET FOR THE PERMANENT EAST 1/2/4 CORNER OF THE NE1/4 OF SECTION 22-20-11
 - 2) 39.85 CHAINS NORTH TO THE STONE THAT HE FOUND AT THE NORTHEAST CORNER OF SECTION 22-20-11
 - 3) 19.76-3/4 CHAINS WEST TO THE POST THAT HE SET FOR THE PERMANENT SOUTH 1/2/4 CORNER OF THE NE1/4 OF SECTION 22-20-11
 - 4) 39.53-1/2 CHAINS WEST TO THE STONE THAT HE FOUND AT THE CENTER CORNER OF SECTION 22-20-11

- 3) JAMES H. BROSEMER, L.S. 82, KDOT CHIEF OF SURVEYS, FOR KDOT PROJECT 57-56-K0548-01, IN 1981, SAID THAT HE EXCAVATED WITH A COUNTY MOTOR GRADER FOR THE STONE AT THE EAST 1/4 CORNER OF SECTION 22-20-11, BUT HE DID **NOT** FIND THE STONE. HE DEEMED THAT THIS CORNER WAS **OBLITERATED**. **HE SET A 1/2" REBAR WITH AN ALUMINUM KDOT CAP STAMPED "E1/4 22-20-11"** FOR THE EAST 1/4 CORNER OF SECTION 22-20-11 BASED ON THE PHYSICAL EVIDENCE THAT HE FOUND AT THIS CORNER; I.E., IN THE CENTER OF THE RIGHT-OF-WAY OF THE NORTH-SOUTH ROAD AND IN LINE WITH A HEDGE AND THE REMAINS OF AN OLD FENCE TO THE WEST.
 - 1) 27.0' NE TO A SPIKE & KDOT WASHER IN THE TOP OF A FENCE POST
 - 2) 20.6' EAST TO A SPIKE & KDOT WASHER IN THE TOP OF A FENCE POST
 - 3) 55.9' SSW TO A SPIKE & KDOT WASHER IN THE TOP OF A CORNER FENCE POST
 - 4) IN LINE WITH A HEDGE TO THE WEST [EXTENDED]
 - 5) A NORTH-SOUTH FENCE IS 20' EAST AND 20' WEST

- 4) STEVEN S. BROSEMER, L.S. 752, IN A LAND SURVEY REFERENCE REPORT DATED MARCH 17, 1988, SAID THAT **HE FOUND THE REBAR WITH THE KDOT ALUMINUM CAP** AT THE EAST 1/4 CORNER OF SECTION 22-20-11 FROM THE EXISTING TIES OF RECORD IN THE COUNTY ENGINEER'S OFFICE BY JAMES H. BROSEMER, L.S. 82, DATED 1981.
 - 1) 26.8' NE TO A PK NAIL & WASHER IN A FENCE POST
 - 2) 29.1' SE TO A PK NAIL & WASHER IN A FENCE POST
 - 3) 20.0' EAST TO A FENCE LINE NORTH-SOUTH
 - 4) 2.0' WEST TO THE CENTERLINE OF TRAVELED WAY OF THE COUNTY ROAD NORTH-SOUTH

WEST QUARTER CORNER 23-20-11