

**WEST 1/16TH CORNER SOUTHEAST QUARTER OF SECTION 24, TOWNSHIP 20 SOUTH,
RANGE 11 EAST**

- 1) BRAD C. ZILLOX, P.S. 889, OF LANDPLAN ENGINEERING, P.A., IN A LAND SURVEY REFERENCE REPORT DATED MAY 14, 2015 FOR PROJECT NUMBER 20151017 FOR AN ALTA/ACSM SURVEY FOR ANSON LAND HOLDING OF THE NORTHWEST 1/4 AND THE NORTH HALF OF THE SOUTHWEST 1/4 AND THE NORTH 120 ACRES OF THE NORTHEAST 1/4 OF SECTION 24-20-11, LARGE SURVEY NUMBER SR #24001 IN THE SURVEY DRAWER FOR TOWNSHIP 20-11, SHOWS ON HIS SURVEY DRAWING THAT **HE SET A 5/8" X 24" IRON BAR WITH HIS "PLS 889" CAP HE SET FOR THE SOUTHEAST CORNER OF THE NORTH 1/2 OF THE SOUTHWEST 1/4 OF SECTION 24-20-11 ON LINE AND HALFWAY BETWEEN THE 5/8" X 320" IRON BAR WITH HIS "PLS 889" CAP HE SET FOR THE SOUTH 1/4 CORNER, AND THE CENTER OF SECTION 24-20-11 THAT FALLS IN A TREE.**

HIS SURVEY DRAWING SHOWS THE FOLLOWING INFORMATION:

- 1) 1,320.45' SOUTH TO THE 5/8" X 30" IRON BAR WITH HIS "PLS 889" CAP HE SET FOR THE SOUTH 1/4 CORNER OF SECTION 24-20-11
- 2) 1,320.46' NORTH TO THE CENTER CORNER OF SECTION 24-20-11 THAT FALLS IN A TREE, WITH TOW 5/8" IRON BARS WITH HIS "PLS 889" CAPS HE SET AS REFERENCE POINTS AT 5' NORTH ON THE QUARTER SECTION LINE AND 5' EAST ON THE QUARTER SECTION LINE
- 3) 2,646.11' WEST TO THE 5/8" X 24" IRON BAR WITH HIS "PLS 889" CAP HE DRILLED INTO THE FRACTURED STONE HE FOUND AT THE WEST 1/4 CORNER OF SECTION 24-20-11

WEST SIXTEENTH CORNER SOUTHEAST QUARTER 24-20-11