

NORTH 1/4 CORNER SECTION 27, TOWNSHIP 20 SOUTH, RANGE 12 EAST

- 1) ON PAGE 555 OF THE GLO ORIGINAL FIELD NOTES IN THE DRAFTING ROOM IN THE COUNTY ENGINEER'S OFFICE IT STATES THAT **THEY SET A LIMESTONE 20" X 16" X 2"** FOR THE 1/4 CORNER BETWEEN SECTIONS 22 & 27-20-12.
THE GOVERNMENT SURVEY NOTES SHOWS THE FOLLOWING INFORMATION:
 - 1) 40.15 CHAINS WEST TO THE 22" X 14" X 2" SANDSTONE THEY SET FOR THE CORNER TO SECTIONS 21, 22, 27 & 28-20-12
 - 2) 40.15 CHAINS EAST TO THE 24" X 14" X 2" SANDSTONE THEY SET FOR THE CORNER TO SECTIONS 22, 23, 26 & 27-20-12

- 2) SAMUEL P. DAVIES, DEPUTY COUNTY SURVEYOR, IN SURVEY NUMBER 61, A **PERMANENT SURVEY** RECORDED IN SURVEY BOOK "B" ON PAGE 59 DATED JUNE 30, 1870 TO ESTABLISH THE 1/4 CORNER OF SECTION 27-20-12 AND ALSO THE CENTER CORNER OF SAID SECTION 27, SAID THAT **HE FOUND THE STONE** AT THE NORTH 1/4 CORNER OF SECTION 27-20-12 ON THIS **PERMANENT SURVEY**.
HIS SURVEY NOTES SHOWS THE FOLLOWING INFORMATION:
 - 1) 79.77 CHAINS SOUTH TO THE STONE THAT HE FOUND AT THE SOUTH 1/4 CORNER OF SECTION 27-20-12

- 3) S. K. McCRARY, DEPUTY COUNTY SURVEYOR, IN SURVEY NUMBER 126, A **PERMANENT SURVEY** RECORDED IN SURVEY BOOK "F" ON PAGE 207 DATED MAY 9, 1905 AT THE REQUEST OF W. C. LONG AND E. B. VAN NESS FOR THE PURPOSE OF LOCATING AND PERMANENTLY ESTABLISHING THE CORNERS AND BOUNDARIES OF THE SOUTHEAST 1/4 OF SECTION 28-20-12 AND RUN SUCH LINES AS MAY BE NECESSARY TO PROPERLY COMPLETE THE WORK, APPARENTLY DID **NOT** FIND THE STONE AT THE SOUTH 1/4 CORNER OF SECTION 22-20-12 AS HE RAN THE SECTION LINES FROM THE STONE THAT HE FOUND IN PLACE AT THE SOUTHWEST CORNER OF SECTION 21-20-12 EAST TO THE STONE THAT HE FOUND IN PLACE AT THE SOUTHEAST CORNER OF SECTION 22-20-12 ON THIS **PERMANENT SURVEY**. HIS FIELD NOTES ARE IN BOOK 2 ON PAGE 148 IN THE "KRETSINGER COLLECTION" OF FIELD BOOKS, AND THERE IS ADDITIONAL INFORMATION IN PACKET "M 157" IN MISCELLANEOUS DRAWER NUMBER 8 IN THE VAULT IN THE COUNTY ENGINEER'S OFFICE.

- 4) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED DECEMBER 3, 2012, FOR PROJECT 12272-02, SAID THAT HE EXCAVATED WITH A COUNTY MAINTAINER FOR THE STONE AT THE SOUTH 1/4 CORNER OF SECTION 22-20-12, BUT HE DID **NOT** FIND THE STONE. HE DEEMED THAT THIS CORNER WAS **LOST**. HE RESET THE SOUTH 1/4 CORNER OF SECTION 22-20-12 ON TRUE LINE AND HALFWAY BETWEEN THE SOUTHWEST CORNER AND THE SOUTHEAST CORNER OF SECTION 22-20-12. **HE SET A 1" X 6" PIPE WITH HIS "LS 752" CAP DUE TO A ROCK LEDGE** FOR THE SOUTH 1/4 CORNER OF SECTION 22-20-12.
 - 1) 25' NE TO A 40 D NAIL & WASHER IN THE EAST SIDE OF A POWER POLE
 - 2) 23.55' NNE TO THE SOUTH SIDE NEAR FACE OF AN 8" PIPE GATE POST
 - 3) 24.9' SOUTH TO A CONCRETE NAIL & WASHER IN A GATE POST
 - 4) 25.0' SOUTH TO A LINE OF FENCE TO THE EAST
 - 5) IN THE TRAVELED WAY EAST-WEST

NORTH QUARTER CORNER 27-20-12