

WEST 1/4 CORNER SECTION 10, TOWNSHIP 21 SOUTH, RANGE 11 EAST

- 1) ON PAGE 419 OF THE GLO ORIGINAL FIELD NOTES IN THE DRAFTING ROOM IN THE COUNTY ENGINEER'S OFFICE IT STATES THAT **THEY SET A LIMESTONE 17" X 10" X 4"** FOR THE 1/4 CORNER BETWEEN SECTIONS 9 & 10-21-11.
- 2) THE KRETSINGER REFERENCE TIE BOOK FOR TOWNSHIP 21-11 SHOWS A **STONE** AT THE "E1/4 CORNER SECTION 9-21-11".
 - 1) 25' EAST TO A CORNER FENCE POST
- 3) KRETSINGER REFERENCE TIE BOOK 13 ON PAGE 66 AT THE BOTTOM OF THE PAGE SHOWS A **CORNERSTONE** AT THE "W1/4 CORNER SECTION 10-21-11".
 - 1) 25' EAST TO THE NEAR FACE OF A CORNER FENCE POST
 - 2) A FENCE BEARS EAST ON THE 1.2 SECTION LINE
- 4) STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED FEBRUARY 20, 1989, SURVEY F10007 IN THE SURVEY FILE FOR TOWNSHIP 20-11 FOR FOUR TRACTS COMPRISING THE OLPE CITY LAKE, LOCATED IN PARTS OF THE NORTHEAST QUARTER, THE SOUTHEAST QUARTER AND THE SOUTHWEST QUARTER OF SECTION 3, AND PART OF THE NORTHWEST QUARTER OF SECTION 10, ALL IN TOWNSHIP 21, RANGE 11, SAID IN HIS *REPORT OF SURVEY* THAT HE EXCAVATED WITH A COUNTY MAINTAINER FOR THE STONE AT THE WEST 1/4 CORNER OF SECTION 10-21-11, BUT HE DID **NOT** FIND THE STONE. HE CONSIDERED THAT THIS CORNER WAS **OBLITERATED**. **HE SET A 1/2" X 24" REBAR WITH HIS "LS 752" CAP** FOR THE WEST 1/4 CORNER OF SECTION 10-21-11 IN LINE WITH FENCES TO THE EAST AND WEST AND IN THE CENTER OF THE NORTH-SOUTH ROAD.
 - 1) 27.7' NE TO A PK NAIL & WASHER IN A GATE POST
 - 2) 32.4' SE TO A PK NAIL & WASHER IN A GATE POST
 - 3) 28.0' WEST TO A FENCE LINE TO THE NORTH
 - 4) 26.0' EAST TO A FENCE LINE NORTH & SOUTH
 - 5) 1.5' EAST TO THE CENTERLINE TRAVELED WAY OF THE COUNTY ROAD

HIS SURVEY DRAWING SHOWS THE FOLLOWING INFORMATION:

 - 1) 1,319.27' NORTH TO THE THEORETICAL POSITION FOR THE WEST 1/16TH CORNER OF THE NW1/4 OF SECTION 10-21-11
 - 2) 2,638.54' NORTH TO THE 1/2" REBAR WITH HIS "LS 752" CAP HE SET FOR THE SOUTHWEST CORNER OF THE SW1/4 OF SECTION 3-21-11
 - 3) 5,276.45' NORTH TO THE GLO SANDSTONE HE FOUND AT THE WEST 1/4 CORNER OF SECTION 3-21-11
 - 4) 8,117.99' NORTH TO THE SPIKE IN ASPHALT HE FOUND AT THE NORTHWEST CORNER OF SECTION 3-21-11 ON THE 4TH STANDARD PARALLEL
 - 5) 1,319.65' EAST TO THE THEORETICAL POSITION FOR THE SOUTH 1/16TH CORNER OF THE NW1/4 OF SECTION 10-21-11
 - 6) 2,639.30' EAST TO THE THEORETICAL POSITION FOR THE SOUTHEAST CORNER OF THE NW1/4 OF SECTION 10-21-11
 - 7) SURVEY COORDINATES: NORTH = 3174.50 EAST = 2,497.80
- 5) WARREN CHIP WOODS, L.S. 603, COUNTY SURVEYOR, IN A LAND SURVEY REFERENCE REPORT DATED SEPTEMBER 23, 1996, FOR LYON COUNTY BRIDGE REPLACEMENT PROJECT NUMBER 96-4N, **FOUND THE 1/2" REBAR WITH THE "BROSEMER LS 752" CAP AT 3" BELOW THE ROAD SURFACE** AT THE WEST 1/4 CORNER OF SECTION 10-21-11 FROM EXISTING TIES OF RECORD IN THE COUNTY ENGINEER'S OFFICE BY STEVEN S. BROSEMER, L.S. 752, DEPUTY COUNTY SURVEYOR, DATED FEBRUARY 20, 1989.

MY TIES ARE ON PAGE 2

- 1) 27.8' NE TO A PK NAIL & WASHER IN A GATE POST
- 2) 24.7' EAST TO A PK NAIL & WASHER IN A CORNER FENCE POST
- 3) 32.4' SE TO A PK NAIL & WASHER IN A GATE POST
- 4) 26.7' WEST TO A PK NAIL & WASHER IN A CORNER FENCE POST
- 5) 44.4' NW TO A PK NAIL & WASHER IN A POWER POLE
- 6) IN LINE WITH FENCES TO THE EAST AND WEST
- 7) 1.5' EAST TO THE CENTERLINE TRAVELED WAY OF COUNTY ROAD "K" NORTH-SOUTH

WEST 1/4 CORNER 10-21-11